


- (SOPSIP)
-
-
-
-
- LPA()
- 0

松下专线一体化管理看板



Part2. production work
order analysis
生产进度分析

Part3. laser carving &
leak detection analysis
镭雕&气密测试分析

Part5. Layered
Process Audit
LPA分层审核



Part1. process flow
video 生产工艺视频

Part4. Quality
Alarm质量警报培训

Part6.work station
operator工位人员看板

可扩展优化，并向其他生产线推广



Part1. process flow video 生产工艺视频



Process flow SOP
全流程生产作业指导



Part2. production work order analysis 生产进度分析





Part3. laser carving & leak detection analysis 镭雕&气密性测试分析



Part4. Quality Alarm 质量警报培训

41-质量警报 29038AA二维码报警原因 20230926

广东威铝铝业股份有限公司
Guangdong Victor Aluminum Co., Ltd.

注意!!!
Attention!!!

质量警报
Quality Alarm

Customer 客户: 3DAA001

Reason 原因: Customer Complaint

Validation Result 验证结果: Permanent Defect

前壳品名: 3CE0029038AA
投入数: 307台
不良数: 1台
不良率: 0.31%
不良内容: 二端均槽碰反

NG OK



注意!

OPR Supervisor
生产主管: 李俊豪

Quality Alarm Training 质量警报培训



2023年10月10日 星期二
PM 13:41:24



松下摄像头洁净室日常点检表



【LV1】班长 每日
晨練

【LV2】PE 每周
刘兴强

監督人

李自梅

【LV2】CQE 每周
假期

[illegible]

Every Day/Week

